

— TIN PLATE MACHINERY. —

TIN, LEAD and PALM OIL
FLUX and BRAN.

Steel Bars and Black Plate.

THE EDWARDS PATENT TIN & TERNE MACHINES. (Economy in tin and labor.)
THE DAVIES & PHILLIPS TINNING, CLEANING, PICKLING & SCOURING MACHINES.
MOREWOOD'S FIVE ROLL TINNING SETS ALL COMPLETE, OR IN PART.
THE LEYSHON PATENT COMPLETE TINNING & CLEANING MACHINES.

CHILLED AND STEEL ROLLS,
ZERO METAL AND MUSHETS STEELS

F. R. PHILLIPS,
IRON, STEEL AND METALS.

200 Walnut Place,
PHILADELPHIA.

March 5th. 189 2.

Colonel O. C. Bosbyshell

Supt. Mint of the United States.

Phila. Pa.

Dear Sir,

I beg to state that I thoroughly examined Rolls this morning & find a slight deflection on one Roll about $\frac{3}{8}$ of an inch from the collar.

This is so minute that it could not be detected by calipering or on the closest examination, except when in use.

It appears that this small flat somewhat interferes with the half dollar tack only.

This is a defect that will be overcome when you take them out to regrind but should not have been permitted. & the writer will duly notify the makers to be careful not to let it occur again.

Yours Obediently,

F. R. Phillips

NARA RG104, Entry 1, Box 175

F.R. Phillips,
Iron, Steel and Metals.
200 Walnut Place,
Philadelphia.
March 5, 1892

Colonel O.C. Bosbyshell
Supt. Mint of the United States
Phila. Pa.

Dear Sir.

I beg to state that I thoroughly examined Rolls this morning & find a slight deflection on one roll about $\frac{3}{8}$ of an inch from the collar.

This is so minute that it could not be detected by calipering or on the closest examination, except when in use.

It appears that this small plat somewhat interferes with the half dollar track only.

This is a defect that will be overcome when you take them out to regrind but should not have been permitted. & the writer will duly notify the makers to be careful not to let it occur again.

Yours Obediently,
F.R. Phillips